National Transportation Safety Board NTSB ID: DEN02LA081 Aircraft Registration Number: N5416 FACTUAL REPORT Occurrence Date: 07/24/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 0745 CO 81084 MDT Two Buttes Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Grumman G-164A Airplane

Narrative

Sightseeing Flight:

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On July 24, 2002, at 0745 mountain daylight time, a Grumman G-164A, N5416, was substantially damaged when the airplane ground-looped while landing at Doyle's Airfield, Two Buttes, Colorado. The commercial pilot, the sole occupant in the airplane, was not injured. The airplane was being operated by the pilot under Title 14 CFR Part 137. Visual meteorological conditions prevailed for the local aerial application flight which originated approximately 30 minutes before the accident. The pilot had not filed a flight plan.

Air Medical Transport Flight:

The pilot said that he was landing with a load of herbicide. During the landing roll, the airplane started to veer to the left. The pilot said he applied right rudder and right brake, but the airplane did not respond. The airplane ground looped to the left, and the right main landing gear separated from the airplane. He said all four wings appeared wrinkled, but the lower right wing was bent up.

Postaccident investigation of the right brake revealed that its master brake cylinder had failed.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA081

Occurrence Date: 07/24/2002

| AVIATION Occ | | | Occurrence Type: Accident | | | | | | | | | |
|--|-----------------------|---|---------------------------|--|---------------|-------------|----------------|----------|-----------------|------------|------------------------|--|
| Landing Facility/Approach In | formation | • | | | | | | | | | | |
| Airport Name | Airport ID: | Airport | Elevation | Runway Used | | Runway Leng | | h R | unway Width | | | |
| Doyle's Airfield NO | | | NONE | 408 | B1 Ft. MSL | . 18 | 0 | 2640 | 2640 | | 60 | |
| Runway Surface Type: Grass/turf | | | | | | · | | | | | | |
| Runway Surface Condition: Dry | | | | | | | | | | | | |
| Type Instrument Approach: Unknown | - own | | | | | | | | | | | |
| VFR Approach/Landing: Full Stop | | | | | | | | | | | | |
| Aircraft Information | | | | | | | | | | | | |
| Aircraft Manufacturer Grumman | | | Model G-16 | /Series 4A | | | | | Serial I | Number | | |
| Airworthiness Certificate(s): Restr | icted (Special) | | | | | | | | | | | |
| Landing Gear Type: Tailwheel | | | | | | | | | | | | |
| Homebuilt Aircraft? No | Number of Seats: | umber of Seats: 1 Certified Max Gross Wt. 2500 LBS Number | | | | | | | r of Engines: 1 | | | |
| • | | | | Engine Manufacturer: Model/Series: Pratt & Whitney R1340 | | | | | | | Rated Power: 600 HP | |
| - Aircraft Inspection Information | | | | | | | • | | | • | | |
| Type of Last Inspection Date | | | | Date of Last Inspection Time | | | nce Last Insp | ection | Airframe | Total Time | | |
| Annual 07 | | | | 07/2002 5 H | | | | | ours 8152 Hours | | | |
| - Emergency Locator Transmitter (| ELT) Information | | | | | | | | | | | |
| ELT Installed? Yes | ELT Operate | ed? No | | | ELT | Aided i | in Locating Ac | cident S | ite? No | | | |
| Owner/Operator Information | | | | | | | | | | | | |
| Registered Aircraft Owner | | | Street / | Address | | | | | | | | |
| Vic L. Doyle | | | | T | State | Zip Code | | | | | | |
| | Street A | Two Buttes CO 81084 Street Address | | | | | | | | | | |
| Operator of Aircraft | | | | | ne as Reg | 'd Aircr | aft Owner | | | | | |
| Same as Reg'd Aircraft Owner | | | | City | | | | | | | Zip Code | |
| Operator Does Business As: Doyle's Ag Services Operator Designator Code: V8DG | | | | | | | | • | | | | |
| - Type of U.S. Certificate(s) Held: N | None | | | | | | | | | | | |
| Air Carrier Operating Certificate(s) | : | | | | | | | | | | | |
| Operating Certificate: | | | | Oper | ator Certific | cate: | | | | | | |
| Regulation Flight Conducted Under | r: Part 137: Agricu | ultural | | • | | | | | | | | |
| Type of Flight Operation Conducted | d: Aerial Application | on | | | | | | | | | | |
| |] | FACTU | JAL REPO | DRT - AV | IATION | | | | | | Page 2 | |

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA081

Occurrence Date: 07/24/2002

| AVIAT | Occurrence Type: Accident | | | | | | | | | | | | |
|--|--|---------------------|---------------------------|-------------------------|-----------|------------|-----------|--------------------|-------------|---------|--------------|---------------|---------------------|
| First Pilot Information | | | | | | | | | | | | | |
| Name | | | | | City | | | | | Stat | te | Date of Birth | Age |
| On File On Fi | | | | | | | le | | | On | File | On File | 36 |
| Sex: M Seat Occupied: Center Principal Profession: Civilian Pilot Certificate | | | | | | | | | | e Numb | oer: On File | - | |
| Certificate(s): Con | nmercial | | | | | | | | | | | | |
| Airplane Rating(s): Sing | gle-engine La | and | | | | | | | | | | | |
| Rotorcraft/Glider/LTA: Non | e | | | | | | | | | | | | |
| Instrument Rating(s): Nor | ie | | | | | | | | | | | | |
| Instructor Rating(s): Non | e | | | | | | | | | | | | |
| Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review? 07/2002 | | | | | | | | | | | | | |
| Medical Cert.: Class 2 | Medica | al Cert. Statu | s: Valid Me | dicalno wa | aivers/li | m. | | Da | te of La | st Me | edical E | xam: 02/2002 | |
| ' | | | | | | | | | | | | | |
| - Flight Time Matrix | All A/C | This Make and Model | Airplane Single Engine | Airplane Mult-Engine | Nigh | t | Actual | Instrument | nstrument F | | | Glider | Lighter Than Air |
| Total Time | 1700 | 300 | 1700 | | | 30 | | | | | | | |
| Pilot In Command(PIC) | 1600 | | | | | | | | | \perp | | | |
| Instructor | | | | | | | | | | \perp | | | |
| Last 90 Days | 140 | | | | | | | | | + | | | |
| Last 30 Days Last 24 Hours | 40 | 4 | 4 | | + | | | -+ | | + | | | |
| Seatbelt Used? Yes | ' | ılder Harness | | | <u> </u> | Tovico | ology Pe | erformed | 12 No. | | 94 | econd Pilot? | |
| Sealbelt Osed: 1 es | 31100 | iluei namess | Oseur res | | | IOXICC | ology i e | ,110111160 | i: NO | | 136 | econd i not: | |
| Flight Plan/Itinerary | | | | | | | | | | | | | |
| Type of Flight Plan Filed: N | one | | | | | | | | | | | | |
| Departure Point | | | | | | State | | Airport | dentifie | r | Depai | rture Time | Time Zone |
| Same as Accident/Incident Location | | | | | | | | NONE | | 0715 | | | MDT |
| Destination | | | | | | State Airg | | Airport Identifier | | | | | |
| Local Flight | | | | | | | | , | | | | | |
| Type of Clearance: None | | | | | | | | | | | | | |
| Type of Airspace: Class | G | | | | | | | | | | | | |
| Weather Information | | | | | | | | | | | | | |
| Source of Briefing: Unknown | own | | | | | | | | | | | | |
| Method of Briefing: Unknown | own | | | | | | | | | | | | |
| | | | FACTUAL | REPORT | - AVIA | TION | ٧ | | | | | | Page 3 |

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DEN02LA081

Occurrence Date: 07/24/2002

| | ETYBOR | | Occurrent | ce Type: | Acciden | ıt | | | | | | |
|---------------|--------------------------|---------------|-------------|------------|-----------|--------------|-------------|-----------------------|------------------------------|-------------|--|---|
| Weather | Information | | | | | | | | | | | |
| WOF ID | Observation Time | Time Zone | WOF Elevati | ion | WOF Di | stance Fr | om Acci | dent Site | Direction From Accident Site | | | е |
| SPD | 0756 | MDT | 4387 Ft. | . MSL | | | | 11 NM | | 220 Deg. Ma | | |
| Sky/Lowes | st Cloud Condition: Clea | ar | | | • | Ft. A | Condition o | | | | | |
| Lowest Ce | Ft. | AGL | Visib | ility: | 10 | SM | Alti | meter: | "Hg | | | |
| Temperatu | ure: 24 °C | 14 °C | Wind | Direction: | 190 | | | Density Altitude: Ft. | | | | |
| Wind Spee | ed: 10 | Gusts: | | Weath | ner Condt | ions at Ac | cident S | ite: Visual C | Cond | itions | | |
| Visibility (F | RVR): Ft. | Visibility (F | RVV) | SM | Intensity | y of Precip | oitation: | | | | | |
| Restriction | s to Visibility: None | | | | | | | | | | | |
| Type of Pro | ecipitation: None | | | | | | | | | | | |
| Accident | Information | | | | | | | | | | | |
| Aircraft Da | Aircraft Fir | e: None | ; | | | Aircraft Exp | losio | n None | | | | |
| Classificati | ion: U.S. Registered/L | J.S. Soil | | | | | | | | | | |
| - Injury Su | mmary Matrix | Fatal S | erious Mino | or | None | TOTAL | | | | | | |
| First Pi | ilot | | | | 1 | | 1 | | | | | |
| Second | d Pilot | | | | | | | | | | | |
| Studen | nt Pilot | | | | | | | | | | | |
| Flight I | nstructor | | | | | | | | | | | |
| Check | Pilot | | | | | | | | | | | |
| Flight E | Engineer | | | | | | | | | | | |
| Cabin / | Attendants | | | | | | | | | | | |
| Other (| Crew | | | | | | | | | | | |
| Passer | ngers | | | | | | | | | | | |
| - TOTAL A | ABOARD - | | | | 1 | | 1 | | | | | |
| Other (| Ground | | | | | | - | | | | | |
| - GRANE | O TOTAL - | | | | 1 | | 1 | | | | | |
| | | ' | 1 | , | | | ' | | | | | |

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DEN02LA081

Occurrence Date: 07/24/2002

Occurrence Type: Accident

| $\Lambda \sim$ | min | intrati | ۰ <i>۱</i> م | ~ f ~ | | いっっ |
|----------------|-----|---------|--------------|-------|-----|-----|
| AΩ | mın | istrati | ve ir | 1IO | rma | uon |

Investigator-In-Charge (IIC)

James F. Struhsaker

Additional Persons Participating in This Accident/Incident Investigation:

Jim Finn Federal Aviation Administration Denver, CO 80249